



STATE WATER RESOURCES CONTROL BOARD

GEOTRACKER

Update

**Sean McClain
Engineering Geologist
San Diego Water Board**





STATE WATER RESOURCES CONTROL BOARD

GEOTRACKER

- **New Reports**
- **Signing up for e-mail alerts**
- **Changes to the Regulatory Profile**
- **The plotting tool**
- **Addition to the mapping**



Regulatory Page

[GEOTRACKER HOME](#) | [PROJECT SEARCH](#) | [SEARCH BY CONTACT](#)

MANAGE MY PROJECTS - OPEN CASES			VISIBLE FIELDS / FILTERS	27 RECORDS FOUND	EXPORT TO EXCEL	PAGE 1 OF 1		
NAME	PROJECT TYPE	STATUS		GO	RESET			
<input type="text"/>	<input type="text"/>	<input type="text"/>						
PROJECT NAME ▼	ADDRESS	CITY	STATUS	GLOBAL ID	LAST REG ACTIVITY	LAST REG RESPONSE	# PAST DUE COMPLIANCE	PENDING ESI
ARCO #5132 PSI#5609	6098 UNIVERSITY AV	SAN DIEGO	OPEN - REMEDIATION	T0607301300	6/2/2014	6/17/2014	0	0
CHATHAM BROTHERS BARREL YARD (FORMER)	2257 BERNARDO AVE	ESCONDIDO	OPEN - REMEDIATION	SL209094184	8/15/2014	9/10/2014	0	0
EAST AUTO SALESTO T0286	696 BROADWAY	CHULA VISTA	OPEN - SITE ASSESSMENT	T0607301832	5/13/2014	6/17/2014	0	0
EL GUERO TIRE SHOP & REPAIR	2401 IMPERIAL AV	SAN DIEGO	OPEN - ASSESSMENT & INTERIM REMEDIAL ACTION	T0607301948	6/21/2014	11/5/2013	1	0
EL NORTE PARKWAY PLAZA	1032 WEST EL NORTE PARKWAY	ESCONDIDO	OPEN - SITE ASSESSMENT	T10000005890	6/30/2014	6/6/2014	0	4
FAIRLANE CLEANERS & LAUNDRY	6505 EL CAJON BL	SAN DIEGO	OPEN - REMEDIATION	T0607300477	12/31/2012	1/20/2011	0	0
FOREIGN CAR SPECIALISTS	256 W MISSION RD	SAN MARCOS	OPEN - SITE ASSESSMENT	T0607302223	7/29/2014	6/4/2013	0	0
FORMER EXXONMOBIL / MTS STATION	745 H ST	CHULA VISTA	OPEN - ASSESSMENT & INTERIM REMEDIAL ACTION	T0607310406	1/30/2014	10/17/2012	1	0
FORMER MOBIL OIL STATION	120 W SAN YSIDRO BL	SAN DIEGO	OPEN - SITE ASSESSMENT	T0607303070	7/22/2014	8/11/2014	0	0
GASOLINE ALLEY	2525 MAIN ST	RAMONA	OPEN - ASSESSMENT & INTERIM REMEDIAL ACTION	T0607302644	5/20/2014	10/23/2012	0	0
HOUSTON CLIFFORD TRUST	1845 ISLAND AV	SAN DIEGO	OPEN - SITE ASSESSMENT	T10000000451	4/11/2014		0	0
J STREET LIQUOR	701 BROADWAY	CHULA VISTA	OPEN - REMEDIATION	T0607302451	7/10/2014	8/8/2014	0	0
KETEMA AEROSPACE & ELECTRONICS FACILITY	790 GREENFIELD DR	EL CAJON	OPEN - REMEDIATION	SL209234198	9/4/2014	8/20/2014	1	0
KINOSHITA FARM SITE	32701 ALIPAZ	SAN JUAN CAPISTRANO	OPEN - REMEDIATION	T10000000266	9/17/2014		0	0
MISSION EXXON	3865 MISSION AV	OCEANSIDE	OPEN - SITE ASSESSMENT	T0607302482	7/31/2014	4/3/2012	0	0
MISSION VALLEY TERMINAL	9950 SAN DIEGO MISSION ROAD	SAN DIEGO	OPEN - REMEDIATION	SL607392800	3/11/2014	1/21/2014	2	0
PACIFIC PETROLEUM	750 N ESCONDIDO BL	ESCONDIDO	OPEN - SITE ASSESSMENT	T06019794859	6/16/2014	1/6/2014	0	0
PALA VISTA GAS STATION	29200 VALLEY CENTER RD	VALLEY CENTER	OPEN - REMEDIATION	T0607399197	8/6/2014	4/9/2012	0	0
PRUDENTIAL OVERALL SUPPLY	740 F ST	CHULA VISTA	OPEN - REMEDIATION	T0607301090	7/1/2013	5/14/2013	0	0
SAN YSIDRO EXXON (FORMER SHELL STATION)	108 W SAN YSIDRO BL	SAN DIEGO	OPEN - SITE ASSESSMENT	T0607302792	7/22/2014	8/11/2014	0	0
SANTA YSABEL (FORMER CHEVRON)	30350 HWY 78	SANTA YSABEL	OPEN - REMEDIATION	T0607302306	12/10/2013	1/6/2014	0	0
SDG&E ENVIRONMENTAL DEPT	1348 SAMPSON ST	SAN DIEGO	OPEN - SITE ASSESSMENT	T06019761425	12/5/2013	9/7/2012	0	0
STAGE STOP LIQUOR	578 MAIN ST	RAMONA	OPEN - REMEDIATION	T0607302418	8/11/2014	7/11/2013	0	0
TOWNE CENTER SERVICE STATION	9305 MISSION GORGE RD	SANTEE	OPEN - ASSESSMENT & INTERIM REMEDIAL ACTION	T0607300542	1/3/2014	4/16/2013	0	0
UNIVAR SAN DIEGO	2100 HAFFLEY AVENUE	NATIONAL CITY	OPEN - SITE ASSESSMENT	T10000005889	6/30/2014	6/5/2014	0	0
WATER TANK RAVINE BURN DUMP (FORMER DEWITT PARCEL)	20300 LAGUNA CANYON ROAD	LAGUNA BEACH	OPEN - SITE ASSESSMENT	T10000003529	8/27/2014	9/3/2014	0	2
WILSON OIL MARKETING CO. #46	685 H ST	CHULA VISTA	OPEN - REMEDIATION	T0607304884	1/30/2014	1/30/2014	0	4

TOOLS

- [Advanced Search](#)
- [Download Data](#)
- [Download ESI Data](#)
- [GeoTracker GAMA](#)
- [Superfund Sites](#)

REPORTS

- [Click to View Reports](#)

UST CASE CLOSURES

- [UST Case Closures for Public Comment](#)

INFORMATION

- [SWRCB Home](#)
- [GeoTracker Fact Sheet](#)
- [GeoTracker GAMA Fact Sheet](#)
- [Electronic Submittal of Information \(ESI\)](#)

Welcome to GeoTracker

Your link to environmental data for regulated facilities in California

MAP LOCATION OF INTEREST

e.g., "10 market st, san francisco, ca" - [INFO](#)

TO SEARCH FOR SPECIFIC CLEANUP SITES, USE THE [ADVANCED SEARCH](#) TOOL

REPORTS

- [Cleanup Sites By County](#)
- [Cleanup Sites By DWR Groundwater Sub-Basin](#)
- [Cleanup Sites By Regional Board Watershed](#)
- [Closure Denial Review Report](#)
- [CUF Open Case Age/Paid Amt/Concentration Report](#)
- [Deed Restrictions / Land Use Restrictions / Covenants](#)
- [Low Threat Closure Policy Summary Report](#)
- [Max Groundwater Concentration Report](#)
- [Max Soil Concentration Report](#)
- [Max Air/Vapor Concentration Report](#)
- [Petitions for Closure to State Water Board](#)
- [Site Type Summary Report](#)
- [Water Purveyor Report for MTBE](#)

[GeoTracker Home](#) [Tools](#) [Reports](#) [Information](#) [SWRCB Home](#)

PETITIONS FOR CLOSURE TO STATE WATER BOARD

157 RECORDS FOUND

[EXPORT TO EXCEL](#)

<u>PETITION ID</u>	<u>PROJECT NAME</u>	<u>ADDRESS</u>	<u>CITY</u>	<u>LEAD AGENCY</u>	<u>DATE PETITION RECEIVED</u>	<u>PRESENT STATUS</u>	<u>ACTION DATE</u>
DWQP-0229	ALL MAKES SMOG & TUNE	555 S ESCONDIDO BL	ESCONDIDO	SAN DIEGO RWQCB (REGION 9)	6/20/2013	Case Closed with Board Order / Resolution	7/29/2014
DWQP-0110	AMERICAN AUTO WRECKERS	3744 DEPOT	HAYWARD	ALAMEDA COUNTY LOP	4/13/2009	Case Closed with Board Order / Resolution	9/21/2010
DWQP-0100	AMERICAN HONDA MOTORS CO. BLDG. 320	1919 TORRANCE BLVD.	TORRANCE	LOS ANGELES RWQCB (REGION 4)	9/20/2007	Active - Under Review	
DWQP-0156	AMERICAN SITE SEARS	8230 SORENSEN AVE	SANTA FE SPRINGS	LOS ANGELES RWQCB (REGION 4)	10/6/2010	Case Closed by Lead Agency / NFA Letter	3/21/2011
DWQP-0112	Andersen Excavating (Andersen, Robert A.)	1175 Cloverdale Blvd S	CLOVERDALE	SONOMA COUNTY LOP	6/17/2009	Case Closed with Board Order / Resolution	8/16/2011
DWQP-0201	ARCO #0206	302 W 1ST	SANTA ANA	ORANGE COUNTY LOP	12/20/2011	Case Closed with Board Order / Resolution	1/29/2014
DWQP-0192	ARCO #1661	9151 PAINTER AVE	WHITTIER	LOS ANGELES RWQCB (REGION 4)	9/14/2011	Case Closed by Lead Agency / NFA Letter	7/16/2012
DWQP-0172	ARCO #1680	5158 LAUREL CANYON BLVD	STUDIO CITY	SWRCB	2/25/2011	Withdrawn by Petitioner	8/20/2012
DWQP-0171	ARCO #1953	15156 GALE AVE. E.	LA PUENTE	LOS ANGELES RWQCB (REGION 4)	2/25/2011	Case Closed by Lead Agency / NFA Letter	7/28/2011
DWQP-0166	ARCO #4495	1950 SOUTH DELAWARE STREET	SAN MATEO	SAN MATEO COUNTY LOP	1/14/2011	Case Closed by Lead Agency / NFA Letter	2/5/2013
DWQP-0173	ARCO #6129	21313 AVALON BLVD S	CARSON	LOS ANGELES RWQCB (REGION 4)	3/7/2011	Active - Under Review	
DWQP-0186	AUBURN MAINTENANCE STATION (CALTRANS)	1050 HWY 49	AUBURN	CENTRAL VALLEY RWQCB (REGION 5S)	6/22/2011	Case Closed by Lead Agency / NFA Letter	6/20/2013
DWQP-0003	AUTOS DEL VALLE	51890 HIGHWAY 86	COACHELLA	RIVERSIDE COUNTY LOP	12/15/1997	Case Closed with Board Order / Resolution	10/22/1998

PACIFIC PETROLEUM (T06019794859) - [\(MAP\)](#)

[SIGN UP FOR EMAIL ALERTS](#)

750 N ESCONDIDO BL
 ESCONDIDO, CA 920251704
 SAN DIEGO COUNTY
 LUST CLEANUP SITE

[PRINTABLE CASE SUMMARY](#)

CLEANUP OVERSIGHT AGENCIES

SAN DIEGO RWQCB (REGION 9) *(LEAD)*

CASEWORKER: [SEAN MCCLAIN](#)

SAN DIEGO COUNTY LOP - CASE #: H03620-002

CUF Claim #: 18827

CUF Priority Assigned: C

CUF Amount Paid: \$318,765

[Summary](#)
[Case Reviews](#)
[Cleanup Action Report](#)
[Regulatory Activities](#)
[Environmental Data \(ESI\)](#)
[Site Maps / Documents](#)
[Community Involvement](#)

[Related Cases](#)
[LUST Fund Data](#)

CASE REVIEWS

<u>TITLE / DESCRIPTION</u>	<u>TYPE</u>	<u>REVIEWED BY</u>	<u>DATE REVIEWED</u>	<u>SUMMARY</u>
LTCP Checklist	LTCP Checklist	SAN DIEGO RWQCB (REGION 9)	6/9/2014	NEFC
Path to Closure Plan	Path to Closure Plan	SAN DIEGO RWQCB (REGION 9)	6/9/2014	
09-42 Closure Review	09-42 Closure Review	SAN DIEGO COUNTY LOP	10/5/2009	NEFC

General Criteria - The site satisfies the policy general criteria**NO**

a. Is the unauthorized release located within the service area of a public water system?

Name of Water System : Vista Irrigation District/ City of Escondido

YES

b. The unauthorized release consists only of petroleum [\(info\)](#).

YES

c. The unauthorized ("primary") release from the UST system has been stopped.

YES

d. Free product has been removed to the maximum extent practicable [\(info\)](#).Free Product Remaining: Measurable Free Product
Removal Methods Tried : HVDPE

NO

e. A conceptual site model that assesses the nature, extent, and mobility of the release has been developed [\(info\)](#).

YES

f. Secondary source has been removed to the extent practicable [\(info\)](#).Impediment to Removing Secondary Source:
- Other - Continue with HVDPE

NO

g. Soil or groundwater has been tested for MTBE and results reported in accordance with Health and Safety Code Section 25296.15.

YES

h. Does a nuisance exist, as defined by [Water Code section 13050](#).

NO

1. Media-Specific Criteria: Groundwater - The contaminant plume that exceeds water quality objectives is stable or decreasing in areal extent, and meets all of the additional characteristics of one of the five classes of sites listed below.**NO****EXEMPTION - Soil Only Case (Release has not Affected Groundwater - [Info](#))****NO**

Does the site meet any of the Groundwater specific criteria scenarios?

NO

ADDITIONAL QUESTIONS - The following conditions exist that do not meet the policy criteria:

Plume Length (That Exceeds Water Quality Objectives) :

- ≥ 250 Feet and $< 1,000$ Feet

Free Product in Groundwater :

- Yes

Free Product Has Been Removed to the Maximum Extent Practicable :

- No

For sites with free product, the Plume Has Been Stable or Decreasing for 5-Years [\(info\)](#) :

- No

For sites with free product, owner Willing to Accept a Land Use Restriction (if required) :

- Unknown

Free Product Extends Offsite :

- Yes

Benzene Concentration :

- $\geq 3,000$ $\mu\text{g/l}$

MTBE Concentration :

- $\geq 1,000$ $\mu\text{g/l}$

2. Media Specific Criteria: Petroleum Vapor Intrusion to Indoor Air - The site is considered low-threat for the vapor-intrusion-to-air pathway if site-specific conditions satisfy items 2a, 2b, or 2c**YES****EXEMPTION - Active Commercial Petroleum Fueling Facility****YES**

IMPEDIMENT 1:

General Criteria D: Free product has NOT been removed to the maximum extent practicable

Step to Resolve Impediment 1 - Step 1:

Demonstrate that free product has been removed to the extent practicable.

COMPLETION DATE

PROJECTED DATE
6/30/2015

ACTUAL DATE

IMPEDIMENT 2:

General Criteria F: Secondary source has NOT been removed to the extent practicable

Step to Resolve Impediment 2 - Step 1:

Demonstrate that the secondary source has been removed to the extent practicable.

COMPLETION DATE

PROJECTED DATE
6/30/2015

ACTUAL DATE

IMPEDIMENT 3:

Media-Specific Criteria: Groundwater: The contaminant plume that exceeds water quality objectives is NOT stable or decreasing in areal extent, and does NOT meet all of the additional characteristics of one of the five classes of sites.

Conditions that do not meet the policy criteria:

- Plume Length (That Exceeds Water Quality Objectives): ≥ 250 Feet and $< 1,000$ Feet
- Free Product in Groundwater: Yes
- Free Product Has Been Removed to the Maximum Extent Practicable: No
- For sites with free product, the Plume Has Been Stable or Decreasing for 5-Years (info): No
- For sites with free product, owner Willing to Accept a Land Use Restriction (if required): Unknown
- Free Product Extends Offsite: Yes
- Benzene Concentration: $\geq 3,000$ $\mu\text{g/l}$
- MTBE Concentration: $\geq 1,000$ $\mu\text{g/l}$

Step to Resolve Impediment 3 - Step 1:

Demonstrate that free product and the secondary source has been removed to the extent practicable.

COMPLETION DATE

PROJECTED DATE
6/30/2015

ACTUAL DATE

IMPEDIMENT 4:

Media Specific Criteria: Direct Contact and Outdoor Air Exposure: The site is NOT considered low-threat for direct contact and outdoor air exposure as it does NOT meet 1, 2, or 3.

Conditions that do not meet the policy criteria:

- Exposure Type: Commercial
- Petroleum Constituents in Soil: > 5 Feet bgs and ≤ 10 Feet bgs
- Soil Concentrations of Benzene: > 14 mg/kg
- Soil Concentrations of EthylBenzene: > 89 mg/kg and ≤ 134 mg/kg

PACIFIC PETROLEUM (T06019794859) - (MAP)

[SIGN UP FOR EMAIL ALERTS](#)

750 N ESCONDIDO BL
 ESCONDIDO, CA 920251704
 SAN DIEGO COUNTY
 LUST CLEANUP SITE
[PRINTABLE CASE SUMMARY](#)

CLEANUP OVERSIGHT AGENCIES
 SAN DIEGO RWQCB (REGION 9) (LEAD)
 CASEWORKER: [SEAN MCCLAIN](#)
 SAN DIEGO COUNTY LOP - CASE #: H03620-002
 CUF Claim #: 18827
 CUF Priority Assigned: C
 CUF Amount Paid: \$318,765

[Summary](#)
[Case Reviews](#)
[Cleanup Action Report](#)
[Regulatory Activities](#)
[Environmental Data \(ESI\)](#)
[Site Maps / Documents](#)
[Community Involvement](#)

[Related Cases](#)
[LUST Fund Data](#)

* DENOTES A SUBMITTAL WAS AUTO-RECEIVED

Individual Well Analytical Data

FIELD POINT NAME	FIELD POINT CLASS	MIN DEPTH TO WATER	MAX DEPTH TO WATER	DEPTH - TOP OF CASING TO WELL SCREEN	LENGTH OF WELL SCREEN	FIELD POINT DESCRIPTION
ED-8	Remediation/Groundwater Monitoring Well	9.62	11.02	5 feet	10 feet	
MW-1	Remediation/Groundwater Monitoring Well	10.51	11.86	5 feet	15 feet	
MW-10	Remediation/Groundwater Monitoring Well	7.65	9.11	5 feet	15 feet	
MW-2	Remediation/Groundwater Monitoring Well	10.00	11.52	5 feet	15 feet	
MW-3	Remediation/Groundwater Monitoring Well	11.23	12.44	5 feet	15 feet	
MW-4	Remediation/Groundwater Monitoring Well	9.82	11.27	5 feet	15 feet	
MW-5	Remediation/Groundwater Monitoring Well	9.72	11.25	5 feet	15 feet	
MW-6	Remediation/Groundwater Monitoring Well	8.53	10.05	5 feet	15 feet	
MW-7	Remediation/Groundwater Monitoring Well	10.60	12.61	5 feet	15 feet	
MW-8	Remediation/Groundwater Monitoring Well	9.02	10.40	5 feet	15 feet	
MW-9	Remediation/Groundwater Monitoring Well	11.28	13.57	5 feet	15 feet	
MW4	Remediation/Groundwater Monitoring Well					
MW5	Remediation/Groundwater Monitoring Well					
MW7	Remediation/Groundwater Monitoring Well					
W-1	Transient Subsurface Sampling Point (i.e. geoprobe.)					
W-2	Transient Subsurface Sampling Point (i.e. geoprobe.)					
	Transient Subsurface Sampling Point (i.e. geoprobe.)					

PACIFIC PETROLEUM (T06019794859) - (MAP)

750 N ESCONDIDO BL
 ESCONDIDO, CA 920251704
 SAN DIEGO COUNTY
 LUST CLEANUP SITE
[PRINTABLE CASE SUMMARY](#)


Analytical Results - MW-4 - [BACK TO REPORT](#)

[Most Recent](#)
[All Data](#)
[Maximum Concentrations](#)

Plot Selected Chemicals
 ☒ PLOT DEPTH-TO-WATER
 ☐ LOGARITHMIC PLOT

PLOT NAME	DATE	PARAMETER
<input type="checkbox"/> MW-4	11/26/2013	BENZENE
<input type="checkbox"/> MW-4	11/26/2013	TOLUENE
<input type="checkbox"/> MW-4	11/26/2013	DI-ISOPROPYL ETHER (DIPE)
<input type="checkbox"/> MW-4	11/26/2013	ETHYLBENZENE
<input type="checkbox"/> MW-4	11/26/2013	ETHYL TERT-BUTYL ETHER (ETBE)
<input type="checkbox"/> MW-4	11/26/2013	GASOLINE RANGE ORGANICS
<input type="checkbox"/> MW-4	11/26/2013	METHYL-TERT-BUTYL ETHER (MTBE)
<input type="checkbox"/> MW-4	11/26/2013	TERT-AMYL METHYL ETHER (TAME)
<input type="checkbox"/> MW-4	11/26/2013	TERT-BUTYL ALCOHOL (TBA)
<input type="checkbox"/> MW-4	11/26/2013	XYLENES

BENZENE Results for MW-4



PACIFIC PETROLEUM (T06019794859) - (MAP)

[SIGN UP FOR EMAIL ALERTS](#)

750 N ESCONDIDO BL
 ESCONDIDO, CA 920251704
 SAN DIEGO COUNTY
 LUST CLEANUP SITE
[PRINTABLE CASE SUMMARY](#)

CLEANUP OVERSIGHT AGENCIES

SAN DIEGO RWQCB (REGION 9) (LEAD)

CASEWORKER: [SEAN MCCLAIN](#)

SAN DIEGO COUNTY LOP - CASE #: H03620-002

CUF Claim #: 18827

CUF Priority Assigned: C

CUF Amount Paid: \$318,765

Summary

Case Reviews

Cleanup Action Report

Regulatory Activities

Environmental Data (ESI)

Site Maps / Documents

Community Involvement

Related Cases

LUST Fund Data

CASE REVIEWS

TITLE / DESCRIPTION	TYPE	REVIEWED BY	DATE REVIEWED	SUMMARY
LTCP Checklist	LTCP Checklist	SAN DIEGO RWQCB (REGION 9)	6/9/2014	NEFC
Path to Closure Plan	Path to Closure Plan	SAN DIEGO RWQCB (REGION 9)	6/9/2014	
09-42 Closure Review	09-42 Closure Review	SAN DIEGO COUNTY LOP	10/5/2009	NEFC

GEO TRACKER


MAP LAYERS

- ☒ Leaking Underground Tank (LUST) Cleanup Sites
- ☐ Other Cleanup Sites
- ☒ Land Disposal Sites
- ☒ Military Sites
- ☒ WDR Sites
- ☒ Non-Case Information
- ☒ Irrigated Lands Regulatory Program
- ☐ Permitted Underground Storage Tank (UST) Facilities
- ☐ CDPH Wells
- ☒ Zoom in to See Field Points
- ☐ DTSC Cleanup Sites
- ☐ DTSC Haz Waste Permit

☒ SIGNIFIES A CLOSED SITE

CLEANUP STATUS FILTER
All Cleanup Statuses

[Measure a Distance](#)



Questions

